

SENSENICH PROPELLER SERVICE, INC.

N601SH

Propeller Logbook

McCauley
Hartzell
MT
Sensenich
Dowty
Hamilton Standard


INSTALLING AGENCY PLEASE NOTE. Recording of Propeller Total Time Since New (TTSM) is Required Per F.A.R. 91.417

Lancaster Airport, 519 East Airport Road, Lititz, PA 17543 (800) 462-3412 (717) 560-3711 Fax: (717) 560-4354 FAA Certified Repair Station #QV9R194N

Lee Gilmore Memorial Airport, 1142 Aviation Boulevard, Gainesville, GA 30501 (800) 791-7767 (770) 538-0444 Fax: (770) 538-0117 FAA Certified Repair Station #S46R346N

Windham County Airport, 21 Airport Road, North Windham, CT 06256 (877) 456-7944 (860) 456-7944 Fax: (860) 456-0410 FAA Certified Repair Station #Q0PR011X

Blade Model	HC-C3YR-2U C8468-8R CK243E
Blade Serial No.	1 <u>B64662</u> 2 <u>B64081</u> 3 <u>B64063</u>
	4
	6



SERVICE HISTORY Date Total Propeller Time Since Overhaul Description of Work Authorized Signature Since Overhaul Description of Work Authorized Signature	SERVICE HISTORY Date Total Propeller Time Since Overhaul Description of Work Authorized Signatures 15-02 Tach 1920.4 DD 94-1213 in day at 1946.2 Xalis. Dannual Asspection Accounting Typ Hotel 102044199
SOUTH COAST PROPELLER SERVICE, INC. 5750 DUROSE DRIVE, BESSEMER, AL 35022 205-426-7022 REPAIR STATION #SEPPROXEX THIS PROPELLER HAS BEEN INSPECTED PER HARTZELL SB HC-SB-61-165E AND AD NOTE 94-17-13 AND FOUND TO BE IN CUITWANTED THE INSPECTION IS DUE AGAIN IN 50 HOURS. THIS INSPECTION WAS PERFORMED BY JONA DOWNING FROM SOUTH COAST PROPELLER SERVICE, INC. 10-04-65	tty condition
OCTOBER 19, 2005 HOBBS: 1790.2 PROP TIME: UNKNOWN 94-17-13 has been complied with and is due again in 50 hrs., 1840.2 Hobbs. I certify this prop has been inspected I/A/W the annual inspection requirements found in the Piper Maintenance Manual and has been determined to be in airworthy condition at this time. MID SOUTH AVIATION INC., Albertville, Al. A&P 418647214 IA Wayne Whisenant	
A&P 418647214 IA Wayne Whisenant	

