

☐ **HUB & BLADE INSPECTIONS, REPAIRS AND ALTERATIONS**

Year: _____ Total
in Ser

SINDELAR AVIATION PO BOX 814 PORTLAND, TN 37148 278 647-1935

Date:

Next Inspection
Due:

Time:
Overh

JUNE 18, 2023

SPOH 422

TACH 4214.5

REMOVED SPINNER, INSPECTED PROP HUB, BLADES AND SPINNER. REINSTALLED
SPINNER.

Year: _____ Total
In Ser

ADS CHECKED THROUGH ISSUE 2023-12.

Date:

I CERTIFY THIS PROPELLER HAS BEEN INSPECTED IN ACCORDANCE WITH AN ANNUAL
INSPECTION AND DETERMINED TO BE IN AN AIRWORTHY CONDITION.

Next Inspection
Due:

Time:
Overh

David C. Sindelar

DAVID C. SINDELAR 2120568 JA

Year: _____ Total
In Service

Date:

Next Inspection
Due:

Time Since
Overhaul

Mech. Cert. # or Repair Station #

Propeller Record General Information

Propeller Manufacturer MCCAULEY

Model 2A36C23-CP6/5-84B0

Hub Series # 664384

Date of Manufacture _____

Type _____

Blade # C478651/5
C480531/5

TRANSPORTATION USD \$6.95

ISBN 978-1-56027-418-6

50695 >

Make/Model

Aircraft Installed On: B25CH V35 N235R

Serial #

D 8360

