

The Standard

PROPELLER LOG

ASA-SPL

Baton Rouge Airport
Customer
Propeller
ITEM
3A32C76-S-M/8824B.2
MODEL
788505
SERIAL NUMBER

"The aircraft propeller or appliance identified above was **OVERHAULED** and inspected in accordance with current regulations of the Federal Aviation Agency and is approved for return to service."
 "Pertinent details of the repair are on file at this repair station under order

No. **N3777** Date **12-22-85**
 Signed **[Signature]** for
 Signature of Authorized Representative

FAA APPROVED REPAIR STATION 208-20

NEW ORLEANS

AIRCRAFT

PROPELLERS, INC.

BOX 395, INDUSTRIAL PARK ROAD
 HAMMOND MUNICIPAL AIRPORT, EAST RAMP
 HAMMOND, LA 70401 • PHONE 504-242-7767

CALL TOLL FREE 1-800-535-2579

OVERHAULED
SERVICEABLE

(OVER)

T, T on A/C
[Signature]

Hammond Municipal Airport - East Ramp
 HAMMOND, LOUISIANA 70401
 (504) 542-9090 242-7767 1 800-535-2579

NOTE: Enter Compliance With All Applicable FAA A.D. & Factory Service Bulletins On Pages 11 & 12

Signature of Authorized Representative

TORY

Authorized Signatures
 Repairman and Station
 Certificate Numbers

Propeller
NB-2
 AA and
 details
 ation on
 attached
 Propeller
 and

MAINTENANCE & SERVICE HISTORY

Date	Total Propeller Time	Time Since Overhaul	Description Of Work	Authorized Signatures Repairman and Station Certificate Numbers
12-3-85	1057 HRS	0	INSTALLED O.H PROP ON BE V35 B	
	S/N D-10205	N 2062 B.	AIRCRAFT GROUND RAMP LEAK CHECKED	
<div> <div>MAINTENANCE RELEASE</div> <div> <p>The aircraft and/or component identified above was repaired and inspected in accordance with current Federal Air Regulations and was found airworthy for return to service. Pertinent details of the repair are on file at this agency.</p> <p>Work Order No. 6326</p> <p>Date 12-3-85</p> <p>Signed [Signature] for Signature of Authorized Individual</p> <p>Approved Repair Station No. 2076</p> </div> </div>				
<div> <div>NOTE: Enter Compliance With All Applicable FAA A.D. & Factory Service Bulletins On Pages 11 & 12</div> <div>BATON ROUGE AIRCRAFT Ryan Airport, Baton Rouge, La.</div> </div>				

Date	Total Propeller Time	Time Since Overhaul	Description Of Work	Authorized Signatures Repairman and Station Certificate Numbers
			Overhauled / Repaired Hunter / McCauley Propeller Model <u>3A32076-1-M</u> / <u>887ND-2</u> S/N <u>788505</u> , in accordance with FAA and Mfg's specifications and regulations. For more details contact this repair station and request information on R/O <u>N3777</u> . Also, see yellow/green tags attached to engine log books with this T. T. and this date. Propeller was installed on A/C <u>N/A</u> and dynamic balanced.	
			Date <u>11-22-85</u> T. T. on A/C <u>11-07-85</u>	<div style="border: 1px solid black; padding: 5px; text-align: center;"> NEW ORLEANS AIRCRAFT PROPELLERS, INC. </div> <hr/> Hammond Municipal Airport East Ramp HAMMOND, LOUISIANA 70401 (504) 542-9090 242-7767 1 800-535-2579

NOTE: Enter Compliance With All Applicable FAA A.D. & Factory Service Bulletins On Pages 11 & 12

NOTE: Enter Compliance With All Applicable FAA A.D. & Factory Service Bulletins On Pages 11 & 12

Signature of Authorized Representative

[Signature]

Date	Total Propeller Time	Time Since Overhaul	Description Of Work	Authorized Signatures Repairman and Station Certificate Numbers
12-3-85	1057 HRS	0	INSTALLED O.H PROP ON BE V35B S/N D-10205 N 2062 B. AIRCRAFT GROUND RAMP LEAK CHECKED	
			<div style="border: 1px solid black; padding: 5px;"> <p align="center">MAINTENANCE RELEASE</p> <p>The aircraft and/or component identified above was repaired and inspected in accordance with current Federal Air Regulations and was found airworthy for return to service. Pertinent details of the repair are on file at this agency.</p> <p>Work Order No. <u>6326</u></p> <p>Date <u>12-3-85</u></p> <p>Signed <u>[Signature]</u> for Signature of Authorized Individual</p> <p>Approved Repair Station <u>fin 2076</u></p> </div>	
<p>NOTE: Enter Compliance With All Applicable FAA A.D. & Factory Service Bulletins On Pages 11 & 12</p>				

NOTE: Enter Compliance With All Applicable FAA A.D.'s & Factory Service Bulletins On Pages 11 & 12

AA A.D. & Factory Se
Ryan Airport, Baton Rouge, La

MAINTENANCE & SERVICE HISTORY


Date	Total Propeller Time	Time Since Overhaul	Description Of Work	Authorized Signatures Repairman and Station Certificate Numbers
3-17-89	1197.8	T.S.O.H 140.5	Reval. lubed and inspected 11/1/89 by HZ w. of 1/2 prop. to be in an unworthy condition	
			MAINTENANCE REPORT	
			The aircraft and/or component above was repaired and in accordance with current FAA Regulations and was found acceptable for return to service. Pertinent data of the repair are on file at this agency.	
			Work Order No. 8150 & 8150	
			Date 3-17-89	
			Signed [Signature] for Signature of Authorized Individual	
			Approved Repair Station No. 2076	
			BATON ROUGE AIRCRAFT	

NOTE: Enter Compliance With All Applicable FAA A.D. & Factory Service Bulletins On Pages 11 & 12

Date	Total Propeller Time	Time Since Overhaul	Description Of Work	Authorized Signatures Repairman and Station Certificate Numbers
6-30-89	1229.04	172.04	Prop removed from Beech V35B S/N D-10205 N 2062B at tach 1229.04 hr. Prop installed on Beech V35B S/N D-10126 N 4701M at tach 724.19. Ground run up & leak check good	<i>Steve Salik</i> ArP 506764251 DENVER AIR CENTER INC. DENVER-JEFFCO AIRPORT BROOMFIELD, COIA 80006


NOTE: Enter Compliance With All Applicable FAA A.D. & Factory Service Bulletins On Pages 11 & 12

MAINTENANCE & SERVICE HISTORY

Date	Total Propeller Time	Time Since Overhaul	Description Of Work	Authorized Signatures Repairman and Station Certificate Numbers
9/27/89	1254	237	Tach Time - 89.11 - dress & paint prop inspected mount bolts & bulk head - spinner o/c -	
			BOB GATES AIRCRAFT MAINTENANCE 200 Racquette Dr. 493-5830 FL Collins, CO 80524	I CERTIFY THAT THIS Propeller has been INSPECTED IN ACCORDANCE WITH AN ANNUAL INSPECTION AND WAS DETERMINED TO BE IN AIRWORTHY CONDITION  1A521806350 5-27-89

NOTE: Enter Compliance With All Applicable FAA A.D. & Factory Service Bulletins On Pages 11 & 12

MAINTENANCE & SERVICE HISTORY

Date	Total Propeller Time	Time Since Overhaul	Description Of Work	Authorized Signatures Repairman and Station Certificate Numbers
10-3-90	1468.66	411.66 -	Tach-963.77, Remove Prop - Rotate 180° & Reinstall, Dress & Paint Blades, Inspect Spinner & Bulk heads.	
			BOB GATES AIRCRAFT MAINTENANCE 200 Racquette Dr. 493-5830 FL Collins, CO 80524	CERTIFY THAT THIS Propeller HAS BEEN INSPECTED IN ACCORDANCE WITH AN ANNUAL INSPECTION AND WAS DETERMINED TO BE IN AIRWORTHY CONDITION  1A521806350

NOTE: Enter Compliance With All Applicable FAA A.D. & Factory Service Bulletins On Pages 11 & 12

F.A.A. AIRWORTHINESS DIRECTIVE AND SERVICE BULLETIN/
LETTER COMPLIANCE RECORD

Date	Total Propeller Time	Time Since Overhaul	A.D./Bulletin/Letter Number	Authorized Signatures Repairman and Station Certificate Numbers
12/10/92	TACH-12	78.29,	TF1783.18, TSPCH-726.18	Ducked blades, painted prop face + tips
				Inspected hub & blades for defects. OK at this time. END
				CERTIFY THAT THIS <u>Propeller</u> HAS BEEN INSPECTED IN ACCORDANCE WITH AN <u>annual</u> INSPECTION AND WAS DETERMINED TO BE IN AIRWORTHY CONDITION.
				<u>Daniel L. Logan</u>
				FA 50590 4232
				BOB GATES AIRCRAFT MAINTENANCE INC. 200 RACQUETTE DRIVE (308) 493-5838 FT. COLLINS, CO 80524

F.A.A. AIRWORTHINESS DIRECTIVE AND SERVICE BULLETIN/ LETTER COMPLIANCE RECORD

Date	Total Propeller Time	Time Since Overhaul	A.D./Bulletin/Letter Number	Authorized Signatures Repairman and Station Certificate Numbers
<p>TRI COUNTY PROPELLERS #FR6R545N MAINTENANCE RELEASE</p> <p>The component identified below was repaired and inspected in accordance with current Federal Air Regulations and was found airworthy for return to service. Pertinent details of the repair are on file at this agency as follows:</p> <p>Work Order # 12912 Date 11/02/93 Propeller <input checked="" type="checkbox"/> Governor <input type="checkbox"/></p> <p>Model # 3A32C76-5-MR/582MB-2 Serial # 788505</p> <p>Overhauled <input checked="" type="checkbox"/> Repaired <input type="checkbox"/> Repitch <input type="checkbox"/> Resealed <input type="checkbox"/> Other <input type="checkbox"/></p> <p>Service Letters Thru 1993-7 Bulletins Thru 205A</p> <p>AD's NA Re-occurring <input type="checkbox"/></p> <p>Next Overhaul Due (hours) 1500 Date 11/2/98</p> <p>Remarks OVERHAULED PROPELLER PER MCCAULEY SERVICE MANUAL 720415.</p> <p>TBO IS 1500 HOURS OR FIVE YEARS WHICHEVER OCCURS FIRST.</p> <p>Cert # PR2349185</p>				

STAPLE MAINTENANCE RELEASE TAGS AND
OTHER DATA TO THIS PAGE

11-17-93 Tock Hrs: 1451.69 Prop TSOH 0.0
Installed prop after OH.

I certify this ^{Prop}engine/airframe has been inspected
in accordance with a ^{Annual} inspection and was
found to be in airworthy condition.
E. L. Gasaway
A&P-1861613 1A

12-10-94 Tock Hrs: 1582.94 Prop TSOH: 131.25
Completed 100/HK/Annual insp this date.
E L Gasaway
A&P 1861613 IA

☐ HUB & BLADE INSPECTIONS, REPAIRS AND ALTERATIONS

Date	Total Time	Time Since Overhaul	Description
12-10-94		131.25	completed 100/Hr/Annual insp + hrs Date. EJ Massey AIP1861613IA
Next Inspection Due: _____ Mech. Cert. # or Repair Station # _____			

Date	Total Time	Time Since Overhaul	Description
12-21-95		343.21	Completed 100 hr/Annual Insp this date. AIP 1861613IA EJ Massey
Next Inspection Due: _____ Mech. Cert. # or Repair Station # _____			

Date	Total Time	Time Since Overhaul	Description
Next Inspection Due: _____ Mech. Cert. # or Repair Station # _____			

☐ HUB & BLADE INSPECTIONS, REPAIRS AND ALTERATIONS

Date	Total Time	Time Since Overhaul	Description
DATE: 1-2-97 TACH: 1950.0 TOTAL TIME: 1950.0 SOH: 498.0 N: 4701M MODEL: 3A32C76-S-MR S/N: 788505			
I certify that this propeller has been inspected in accordance with a 100 hour inspection and was determined to be in airworthy condition.			

Next I

D

BOB GATES AIRCRAFT MAINTENANCE, INC.
200 Racquette Dr.
Ft. Collins, CO 80524
970-493-5838

James E. Crisman
A&P504702960

Next I

Date	Total Time	Time Since Overhaul	Description
Next Inspection Due: _____ Mech. Cert. # or Repair Station # _____			

MOUNTAIN FLIGHT SERVICE INC.

P.O. Box 772849, Steamboat Springs, CO 80477 (970)870-8986 Fax (970)870-8986

BEECHCRAFT V35B N4701M S/N D10126 TACH TIME 2119.82

McCauley 3A32C76-S-MR S/N 7885051/9/98

Airworthiness Directives are current through 1-9-98. I certify that this propeller has been inspected in accordance with a 100 hour inspection is determined to be in airworthy condition and is approved for return to service. James R. Szabo A&P154541311IA *James R Szabo*

MOUNTAIN FLIGHT SERVICE INC.

P.O. Box 772849, Steamboat Springs, CO 80477 (970)870-8986 Fax (970)870-8986

BEECHCRAFT V35B N4701M S/N D10126 TACH TIME 2248.46

McCauley 3A32C76-S-MR S/N 788505 TSO 796.46 1/18/99

Dressed blades as necessary. Airworthiness Directives are current through 99-01. I certify that this propeller has been inspected in accordance with a 100 hour inspection is determined to be in airworthy condition and is approved for return to service. James R. Szabo A&P154541311IA *James R Szabo*

MOUNTAIN FLIGHT SERVICE INC.

P.O. Box 772849, Steamboat Springs, CO 80477 (970)870-8986 Fax (970)870-8986

BEECHCRAFT V35B N4701M S/N D10126 TACH TIME 2352.0

McCauley 3A32C76-S-MR S/N 788505 TSO 900.3 2/14/2000

Dressed blades as necessary. Airworthiness Directives are current through 2-14-2000. I certify that this propeller has been inspected in accordance with a 100 hour inspection is determined to be in airworthy condition and is approved for return to service. James R. Szabo A&P154541311IA *James R Szabo*

MOUNTAIN FLIGHT SERVICE INC.

P.O. Box 772849, Steamboat Springs, CO 80477 (970)870-8986 Fax (970)870-8986

BEECHCRAFT V35B N4701M S/N D10126 TACH TIME 2415.53

McCauley 3A32C76-S-MR S/N 788505 TSO 963.6 2/17/2001

Dressed blades as necessary. Airworthiness Directives are current through 2000-03. I certify that this propeller has been inspected in accordance with a 100 hour inspection is determined to be in airworthy condition and is approved for return to service. James R. Szabo A&P154541311IA *James R Szabo*

SEE OTHER SIDE

Maintenance Release

Part McCauley Propeller

Model 3A32C76MR

The component identified above was ~~repaired~~
overhauled and inspected in accordance with
current Federal air regulations and was found
air-worthy for return to service. Pertinent details
of the repair are on file at this agency under Work
Order No. 14410

Date 3-16-03

Signed [Signature]

Authorized individual

PRECISION PROPELLER SERVICE, INC.

Weld County Municipal Airport
631 Buss Ave., Greeley, CO 80631

(970) 352-8578

FAA APPROVED REPAIR STATION
NO. UB3R887L

propeller
and is

DATE: 3/25/03 TACH: 2570.0 N: 4701M MODEL: V35B S/N: D-10126 TOTAL TIME: 2570.0

ENGINE MODEL: IO-550-B S/N: 281861-6 TOTAL TIME: 1118.07

MODEL: 3A32C76-S-MR S/N: 788505 TOTAL TIME: 2570.0 SOH: 1118.07

Prop removed and reinstalled after overhaul by Precision Propeller (see yellow tag)

I certify that this propeller has been inspected in accordance with an annual inspection and was
determined to be in airworthy condition.

[Signature]

Gerald L. Gates
A&P5248062521A

BOB GATES AIRCRAFT MAINTENANCE, INC.

200 Racquette Dr.

Ft. Collins, CO 80524

970-493-5838

Date	Total Time	Time Since Overhaul	Description
------	------------	---------------------	-------------

Next Inspection Due: _____ Mech. Cert. # or Repair Station # _____

Next Inspection Due: _____

Mech. Cert. # or Repair Station # _____

Make McCauley

S/N 788505

Model 3A32C76MR/82NB-2

S/N 788505

Blades 1 F69652YS 2 K90270YS 3 K90307YS 4

Overhauled

Blades Rep.

—Blade Repair

Research

Repitch _

Other.

Service Manual

Service Letters

as applicable through 01-1E

Service Bulletins²

as applicable through 227B

AD's n/a

- Boot P/N.

Remarks

complete propeller overhauled

Pitch Settings: Low

14.2

High

34.5

Reverse

TSO 0


π

Feather

Latch

P.O. Box 772849, Steamboat Springs, CO 80477 (970)870-8986 Fax (970)870-8986

BEECHCRAFT V35B N4701M S/N D10126 TACH TIME 2491.24
TCM IO-550-B S/N 281861-6 TIME SINCE OVERHAUL 1039.31 2-28-2002
M. G. 3432C76-S-MR S/N 788505 TSO 1039.31

Dressed blades as necessary. Airworthiness Directives are current through 2002-04. I certify that this propeller has been inspected in accordance with a 100 hour inspection is determined to be in airworthy condition and is approved for return to service. James R. Szabo A&P154541311LA 

ext Inspection Due: _____ Mech. Cert. # or Repair Station # _____

Date _____

Total Time

Time Since Overhaul

Description

Next Inspection Due: _____ Mech. Cert. # or Repair Station # _____

DATE: 5/1/04 TACH: 2741.0 N: 4701M MODEL: V35B S/N: D-10126 TOTAL TIME: 2741.0
ENGINE MODEL: IO-550-B S/N: 281861-6 TOTAL TIME: XXXXXXXXXX 1289.07
MODEL: 3A32C76-S-MR S/N: 788505 TOTAL TIME: 2741.0 SOH: 1289.07

Filed and painted propeller

I certify that this propeller has been inspected in accordance with an **annual** inspection and was determined to be in airworthy condition.

Gerald L. Gates A&P524806252IA

BOB GATES AIRCRAFT MAINTENANCE, INC.
200 Racquette Dr.
Ft. Collins, CO 80524
970-493-5838



Next Inspection Due: _____ Mech. Cert. # or Repair Station # _____

Date	Total Time	Time Since Overhaul	Description

Next Inspection Due: _____ Mech. Cert. # or Repair Station # _____

HUB & BLADE INSPECTIONS, REPAIRS AND ALTERATIONS ☐

Mountain Aircraft Maintenance, Inc

P.O. Box 772114, Steamboat Springs, CO 80477
(970) 870-8986 Fax (970) 870-0387

2873.34
April 22, 2005 Tach 2873.34 Total Time ~~3378.19~~ 2873.34 TSMOH 303.34
N4701M McCauley 3A32C76MR S/N 788505

I certify this propeller has been inspected in accordance with an **annual** inspection and was determined to be in airworthy condition.



Brent P Higgins A&P3038587 IA

Next Inspection Due: _____ Mech. Cert. # or Repair Station # _____

Mountain Aircraft Maintenance, Inc

P.O. Box 772114, Steamboat Springs, CO 80477

(970) 870-8986 Fax (970) 870-0387

McCauley 3A32c76MR S/N 788505

5/16/2006 Tach 2917.72 Total Time 2917.72

N4701M Beechcraft V35B S/N D10126

- AD 03-13-17, does not apply by serial number of propeller installed.

- AD 05-14-11, no record of service on propeller by Southern California Propeller.

I certify that this propeller has been inspected in accordance with an ANNUAL inspection and was determined to be in airworthy condition.



Brent P Higgins A&P 3038587 IA

Next Inspection Due: _____ Mech. Cert. # or Repair Station # _____

Date	Total Time	Time Since Overhaul	Description
------	------------	---------------------	-------------

Next Inspection Due: _____ Mech. Cert. # or Repair Station # _____

HUB & BLADE INSPECTIONS, REPAIRS AND ALTERATIONS

Date	Total Time	Time Since Overhaul	Description
------	------------	---------------------	-------------

Mountain Aircraft Maintenance, Inc P.O. Box 772114, Steamboat Springs, CO 80477
(970) 870-8986

Next **N:4701M Make: 3A32C76 S/N: 788505 TACH: 2942.86 TTP: 2942.86 TSPOH: 1490.86 Date: 07/02/07**

Complete 100 Hour Inspection this date in accordance with FAR part 43 appendix D and checklist. Performed visual inspection of hub and blades for cracks. Inspected spinner and bulkheads for cracks. Removed and replaced forward spinner bulkhead and shimmed as required. Inspected blades for condition and dressed leading edges as required. Painted blade tips and faces. I certify that this propeller has been inspected in accordance with a 100 Hour

Next Inspection and was determined to be in an airworthy condition. W.O. 0607 - END -

DANIEL L. INGRAM

A&P3014106



Next Inspection Due: _____ Mech. Cert. # or Repair Station # _____

☐ A Mountain Aircraft Maintenance, Inc

P.O. Box 772114, Steamboat Springs, CO 80477 (970) 870-8986 Fax (970) 870-0387

July 8, 2008 Tach and Total Time 2967.41 Prop SMOH 397.41
N4701M McCauley 3A32C76-S-MR S/N 788505

I certify that this propeller has been inspected in accordance with a 100 Hour / ANNAUL inspection and was determined to be in airworthy condition.



Next

John C Duffy A&P 470702453 IA

Mountain Aircraft Maintenance, Inc

P.O. Box 772114, Steamboat Springs, CO 80477 (970) 870-8986 Fax (970) 870-0387

August 14, 2009 Tach and Total Time 2985.92 Prop SMOH 415.92
N4701M McCauley 3A32C76-S-MR S/N 788505

Dressed nicks in leading edge of blades as required. I certify that this propeller has been inspected in accordance with a 100 Hour / ANNUAL inspection and was determined to be in airworthy condition.



Next

John C Duffy A&P 470702453 IA

Mountain Aircraft Maintenance Inc.

P.O. Box 772114, Steamboat Springs, CO 80477 PH: 970-870-8986

N: 4701M MAKE: McCauley 3a32C76-S-MR S/N: 788505 TACH: 3005.94 SPOH: 0435.94 DATE: 09/17/10

Complete 100 Hour Inspection this date in accordance with FAR PART 43, appendix D and checklist. Inspected Performed visual inspection of blades for condition. And hub for cracks and leaks. Inspected spinner and bulkheads for cracks. Dressed blades and painted tips and faces as required. Checked applicable AD's through Bi-weekly issue 2010-16. See AD list in aircraft forms for complete listing with effective dates. I certify that this propeller has been inspected in accordance with a 100 Hour Inspection and was determined to be in an Airworthy condition. W.O. 0902 - END -

Daniel L. Ingram
A&P 3014106




Mountain Aircraft Maintenance, Inc

P.O. Box 772114, Steamboat Springs, CO 80477 (970) 870-8986 Fax (970) 870-0387

November 1, 2011 Tach and Total Time 3006.9 Prop SMOH 436.9
N4701M McCauley 3A32C76-S-MR S/N 788505

I certify that this propeller has been inspected in accordance with a 100 Hour / ANNUAL inspection and was determined to be in airworthy condition. John C Duffy A&P 3491366 IA



Mountain Aircraft Maintenance, Inc

P.O. Box 772114, Steamboat Springs, CO 80477 (970) 870-8986 Fax (970) 870-0387

January 2, 2013 Tach and Total Time 3007.78 Prop SMOH 437.78
N4701M McCauley 3A32C76-S-MR S/N 788505

I certify that this propeller has been inspected in accordance with a 100 Hour inspection and was determined to be in airworthy condition. John C Duffy A&P 3491366 IA



Mountain Aircraft Maintenance, Inc

P.O. Box 772114, Steamboat Springs, CO 80477 (970) 870-8986 Fax (970) 870-0387

June 25, 2015 Tach and Total Time 3008.22 Prop SMOH 438.22
N4701M McCauley 3A32C76-S-MR S/N 788505

I certify that this propeller has been inspected in accordance with a 100 Hour inspection and was determined to be in airworthy condition. John C Duffy A&P 3491366 IA



AIRWORTHINESS DIRECTIVES ☐

Complied by the following:

DATE: 07-07-16

N4701M PROP

TACH: 3084.36

TSN:514.36

Performed annual inspection I/A/W Beech V35 MM. See AD listing For AD compliance. I certify this Propeller has been inspected I/A/W an annual inspection and was determined to be in airworthy condition

David Sanford IA 3032129

Next Inspection Due: Mech. Cert. # or Repair Station #

A.D. #

Date

Total Hours

Complied by the following:

04 Aug 2017 TACH 3187.9 - INSPECTED for Condition - OK -
S.D. 3492959 AP

Next Inspection Due: Mech. Cert. # or Repair Station #

October 1, 2018

Tach: 3272.13, TSN: 702.13

This propeller has been inspected IAW FAR Part 43, Appendix D scope and detail of an annual inspection and determined airworthy.



James DeHaven
AP 3114836 IA

Factory Bulletin #	Date	Total Time	Complied by the following:

Next Inspection Due: _____ Mech. Cert. # or Repair Station # _____

FACTORY BULLETINS ☐

Factory Bulletin #	Date	Total Time	Complied by the following:

Next Inspection Due: _____ Mech. Cert. # or Repair Station # _____

Factory Bulletin #	Date	Total Time	Complied by the following:

Next Inspection Due: _____ Mech. Cert. # or Repair Station # _____